



RS56P

**#6 Stranded Copper Conductor
to
#5 Reinforcing Bar**

Description

#6 Stranded Copper Conductor to #5 Reinforcing Bar
Horizontal thru Cable to Side of Vertical Reinforcing Steel

(1) #WRPSLV Wrap Sleeve required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US90	NUWTUBE90	MH1