

**RS51/0P**

**1/0 Stranded Copper Conductor  
to  
#5 Reinforcing Bar**

**Description**

---

1/0 Stranded Copper Conductor to #5 Reinforcing Bar  
Horizontal thru Cable to Side of Vertical Reinforcing Steel

(1) #WRPSLV Wrap Sleeve required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US115	NUWTUBE115	MH1