



**RS46P**

**#6 Stranded Copper Conductor  
to  
#4 Reinforcing Bar**

**Description**

---

#6 Stranded Copper Conductor to #4 Reinforcing Bar  
Horizontal thru Cable to Side of Vertical Reinforcing Steel

(1) #WRPSLV Wrap Sleeve required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US90	NUWTUBE90	MH1