



RS43/0P

**3/0 Stranded Copper Conductor
to
#4 Reinforcing Bar**

Description

3/0 Stranded Copper Conductor to #4 Reinforcing Bar
Horizontal thru Cable to Side of Vertical Reinforcing Steel

(1) #WRPSLV Wrap Sleeve required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US150	NUWTUBE150	MH1