



**RS42/0P**

**2/0 Stranded Copper Conductor  
to  
#4 Reinforcing Bar**

**Description**

---

2/0 Stranded Copper Conductor to #4 Reinforcing Bar  
Horizontal thru Cable to Side of Vertical Reinforcing Steel

(1) #WRPSLV Wrap Sleeve required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US115	NUWTUBE115	MH1