



RS41/0P

**1/0 Stranded Copper Conductor
to
#4 Reinforcing Bar**

Description

1/0 Stranded Copper Conductor to #4 Reinforcing Bar
Horizontal thru Cable to Side of Vertical Reinforcing Steel

(1) #WRPSLV Wrap Sleeve required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US115	NUWTUBE115	MH1