



**RP41/0B**

**1/0 Stranded Copper Conductor  
to  
#4 Reinforcing Bar**

**Description**

---

1/0 Stranded Copper Conductor to #4 Reinforcing Bar  
Parallel Cable Tap of Horizontal Cable to Thru Horizontal Reinforcing Steel

(2) #WRPSLV Wrap Sleeves required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US90	NUWTUBE90	MH1