



RP33/0B

**3/0 Stranded Copper Conductor
to
#3 Reinforcing Bar**

Description

3/0 Stranded Copper Conductor to #3 Reinforcing Bar
Parallel Cable Tap of Horizontal Cable to Thru Horizontal Reinforcing Steel

(2) #WRPSLV Wrap Sleeves required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US115	NUWTUBE115	MH1