



RE46B

**#6 Stranded Copper Conductor
to
#4 Reinforcing Bar**

Description

#6 Stranded Copper Conductor to #4 Reinforcing Bar
Tee of Vertical Thru Reinforcing Steel & Horizontal Tap Cable

(1) #WRPSLV Wrap Sleeve required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US45	NUWTUBE45	MH1