



RB34B

**#4 Stranded Copper Conductor
to
#3 Reinforcing Bar**

Description

#4 Stranded Copper Conductor to #3 Reinforcing Bar
Tee of Horizontal Thru Reinforcing Steel & Horizontal Tap Cables

(2) #WRPSLV Wrap Sleeves required per weld

| UltraShot Weld Metal | NUWTube Weld Metal | Mold Handle |
|----------------------|--------------------|-------------|
| US45 | NUWTUBE45 | MH1 |