



## PT46SB

**#6 Solid Copper Conductor  
to  
#4 Stranded Copper Conductor**

### Description

---

#6 Solid Copper Conductor to #4 Stranded Copper Conductor  
Parallel Thru Splice of Horizontal Cables, Tap Conductor Over Run

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US32	NUWTUBE32	MH1