



PB46SB

**#6 Solid Copper Conductor
to
#4 Stranded Copper Conductor**

Description

#6 Solid Copper Conductor to #4 Stranded Copper Conductor
Parallel Tap of Horizontal Cables

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US32	NUWTUBE32	MH1