



RB32B

**#2 Stranded Copper Conductor
to
#3 Reinforcing Bar**

Description

#2 Stranded Copper Conductor to #3 Reinforcing Bar
Tee of Horizontal Thru Reinforcing Steel & Horizontal Tap Cables

(2) #WRPSLV Wrap Sleeves required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US65	NUWTUBE65	MH1