



RB46B

#6 Stranded Copper Conductor to #4 Reinforcing Bar

Description

#6 Stranded Copper Conductor to #4 Reinforcing Bar
Tee of Horizontal Thru Reinforcing Steel & Horizontal Tap Cables

(2) #WRPSLV Wrap Sleeves required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US45	NUWTUBE45	MH1