



RB56B

**#6 Stranded Copper Conductor
to
#5 Reinforcing Bar**

Description

#6 Stranded Copper Conductor to #5 Reinforcing Bar
Tee of Horizontal Thru Reinforcing Steel & Horizontal Tap Cables

(2) #WRPSLV Wrap Sleeves required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US90	NUWTUBE90	MH1