



**RB62B**

**#2 Stranded Copper Conductor  
to  
#6 Reinforcing Bar**

**Description**

---

#2 Stranded Copper Conductor to #6 Reinforcing Bar  
Tee of Horizontal Thru Reinforcing Steel & Horizontal Tap Cables

(2) #WRPSLV Wrap Sleeves required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US90	NUWTUBE90	MH1