



## RO42B

### #2 Stranded Copper Conductor to #4 Reinforcing Bar

#### Description

---

#2 Stranded Copper Conductor to #4 Reinforcing Bar  
Cross of Horizontal Cable Lapped Over Horizontal Reinforcing Steel

(2) #WRPSLV Wrap Sleeves required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US90	NUWTUBE90	MH1