



## RO46B

### #6 Stranded Copper Conductor to #4 Reinforcing Bar

#### Description

---

#6 Stranded Copper Conductor to #4 Reinforcing Bar  
Cross of Horizontal Cable Lapped Over Horizontal Reinforcing Steel

(2) #WRPSLV Wrap Sleeves required per weld

| UltraShot Weld Metal | NUWTube Weld Metal | Mold Handle |
|----------------------|--------------------|-------------|
| US65                 | NUWTUBE65          | MH1         |