



**RP36B**

**#6 Stranded Copper Conductor  
to  
#3 Reinforcing Bar**

**Description**

---

#6 Stranded Copper Conductor to #3 Reinforcing Bar  
Parallel Cable Tap of Horizontal Cable to Thru Horizontal Reinforcing Steel

(2) #WRPSLV Wrap Sleeves required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US25	NUWTUBE25	MH1