



RP42/0B

**2/0 Stranded Copper Conductor
to
#4 Reinforcing Bar**

Description

2/0 Stranded Copper Conductor to #4 Reinforcing Bar
Parallel Cable Tap of Horizontal Cable to Thru Horizontal Reinforcing Steel

(2) #WRPSLV Wrap Sleeves required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US90	NUWTUBE90	MH1