



RP4L2SA

**#2 Solid Copper Conductor
to
#4 & Larger Reinforcing Bar**

Description

#2 Solid Copper Conductor to #4 & Larger Reinforcing Bar
Parallel Cable Tap of Horizontal Cable to Thru Horizontal Reinforcing Steel

(1) #CERPM1 Ceramic Packing Material required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US45	NUWTUBE45	Included