



## RP4L6A

### #6 Stranded Copper Conductor to #4 & Larger Reinforcing Bar

#### Description

---

#6 Stranded Copper Conductor to #4 & Larger Reinforcing Bar  
Parallel Cable Tap of Horizontal Cable to Thru Horizontal Reinforcing Steel

(1) #CERPM1 Ceramic Packing Material required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US25	NUWTUBE25	Included