# ULTRASH T®

### **Five Steps to the Perfect Connection**



**step**Dry and Clean the mold and conductor.



step Z
Place conductors and UltraShot cartridge into mold.



step 5
Close the lid and attach DRONE cord to the UltraShot igniter.



step 4
Push and hold both igniter buttons at the same time.



step 5
Reaction is made, open mold to remove connection and clean mold before next connection.



A completed UltraShot® connection

## IIITRASH T Advantages



#### **Ultraweld® Provides Superior Molds**

- Ultraweld® molds are more durable than those of other. manufacturers.
- · Harger uses high durability graphite.
- · Strong precision hinges are used in the construction of Ultraweld® molds.

#### **UltraShot® Drone Ignition Process**

- DRONE Electronic Ignition with Audible Alert and 6' Cord
- · 2 Button Safety Feature
- Over 1,300 Connections on a Single Charge
- Milwaukee
- Utilizes a Milwaukee<sup>®</sup> M18<sup>™</sup> REDLITHIUM<sup>™</sup> XC 4.0 18 volt Battery and Milwaukee® M18™ & M12™ Multi-Voltage Charger.





#### **Ultraweld® Innovative Mold Designs**

- Ultraweld® molds are designed to take either UltraShot®, NUWTube® or Low-Smoke systems.
- Two-Piece mold designs for six different mold families (GS, XO, RE, RO, RP and RS) which improves usability and lowers cost.





#### **Patented Mold Handle Clamps with Modular Attachments**

- Patented handle clamps include a set of mounting holes for a variety of attachments and an offset design to increase versatility.
- Mounting holes allow for a variety of attachments including:
  - Magnetic Kits for flat steel surfaces
  - Chain Kits for vertical and horizontal round members
  - A set of Mold Stabilizer Spikes when working in trenches
  - A Vertical Handle for special applications
- The patented handle mounting holes and the innovative mold designs allow for any full size mold to be converted to a Low Smoke-No Flame mold.
- Ultraweld® attachments are significantly lower in cost than the bulky clamp assemblies offered by other manufacturers.

Harger does not penalize you for expedited same day or next day service! No additional charges for non-stocked or specialty designed molds!



#### **Harger Lightning & Grounding**

301 Ziegler Drive, Grayslake, IL 60030 847.548.8700 • 800.842.7437

Website: www.harger.com • Email: hargersales@harger.com