



PT4/02SB

#2 Solid Copper Conductor to 4/0 Stranded Copper Conductor

Description

#2 Solid Copper Conductor to 4/0 Stranded Copper Conductor
Parallel Thru Splice of Horizontal Cables, Tap Conductor Over Run

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US150	NUWTUBE150	MH1