

**RS7L1/0B**

**1/0 Stranded Copper Conductor  
to  
#7 & Larger Reinforcing Bar**

**Description**

---

1/0 Stranded Copper Conductor to #7 & Larger Reinforcing Bar  
Horizontal thru Cable to Side of Vertical Reinforcing Steel

(1) #CERPM3 Ceramic Packing Material required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US115	NUWTUBE115	MH1