



RP38SB

#8 Solid Copper Conductor to #3 Reinforcing Bar

Description

#8 Solid Copper Conductor to #3 Reinforcing Bar
Parallel Cable Tap of Horizontal Cable to Thru Horizontal Reinforcing Steel

(2) #WRPSLV Wrap Sleeves required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US25	NUWTUBE25	MH1