



RE33/0B

**3/0 Stranded Copper Conductor
to
#3 Reinforcing Bar**

Description

3/0 Stranded Copper Conductor to #3 Reinforcing Bar
Tee of Vertical Thru Reinforcing Steel & Horizontal Tap Cable

(1) #WRPSLV Wrap Sleeve required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US150	NUWTUBE150	MH1