

**PT46B****#6 Stranded Copper Conductor
to
#4 Stranded Copper Conductor****Description**

#6 Stranded Copper Conductor to #4 Stranded Copper Conductor
Parallel Thru Splice of Horizontal Cables, Tap Conductor Over Run

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US32	NUWTUBE32	MH1