



PB26B

#6 Stranded Copper Conductor to #2 Stranded Copper Conductor

Description

#6 Stranded Copper Conductor to #2 Stranded Copper Conductor
Parallel Tap of Horizontal Cables

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US32	NUWTUBE32	MH1