



PB1/06B

#6 Stranded Copper Conductor to 1/0 Stranded Copper Conductor

Description

#6 Stranded Copper Conductor to 1/0 Stranded Copper Conductor
Parallel Tap of Horizontal Cables

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US45	NUWTUBE45	MH1