



## HRCT46SB

### #6 Solid Copper Conductor to #4 Reinforcing Bar

#### Description

---

#6 Solid Copper Conductor to #4 Reinforcing Bar  
Horizontal Reinforcing Bar Cable Thru

(2) #WRPSLV Wrap Sleeves required per weld (2) #WRPSLV Wrap Sleeves required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US90	NUWTUBE90	MH1