

**HRCT6L2SB**

**#2 Solid Copper Conductor
to
#6 & Larger Reinforcing Bar**

Description

#2 Solid Copper Conductor to #6 & Larger Reinforcing Bar
Horizontal Reinforcing Bar Cable Thru

(1) #CERPM2 Ceramic Packing Material required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US90	NUWTUBE90	MH1