



PB1/06SB

**#6 Solid Copper Conductor
to
1/0 Stranded Copper Conductor**

Description

#6 Solid Copper Conductor to 1/0 Stranded Copper Conductor
Parallel Tap of Horizontal Cables

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US45	NUWTUBE45	MH1