

**PB4/02B****#2 Stranded Copper Conductor  
to  
4/0 Stranded Copper Conductor****Description**

---

#2 Stranded Copper Conductor to 4/0 Stranded Copper Conductor  
Parallel Tap of Horizontal Cables

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US115	NUWTUBE115	MH1