



## PB4/02SB

**#2 Solid Copper Conductor  
to  
4/0 Stranded Copper Conductor**

### Description

---

#2 Solid Copper Conductor to 4/0 Stranded Copper Conductor  
Parallel Tap of Horizontal Cables

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US115	NUWTUBE115	MH1