



PB4/04B

#4 Stranded Copper Conductor to 4/0 Stranded Copper Conductor

Description

#4 Stranded Copper Conductor to 4/0 Stranded Copper Conductor
Parallel Tap of Horizontal Cables

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US90	NUWTUBE90	MH1