



PB4/06B

#6 Stranded Copper Conductor to 4/0 Stranded Copper Conductor

Description

#6 Stranded Copper Conductor to 4/0 Stranded Copper Conductor
Parallel Tap of Horizontal Cables

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US90	NUWTUBE90	MH1