



PB4/06SB

**#6 Solid Copper Conductor
to
4/0 Stranded Copper Conductor**

Description

#6 Solid Copper Conductor to 4/0 Stranded Copper Conductor
Parallel Tap of Horizontal Cables

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US90	NUWTUBE90	MH1