



**RB34/0B**

**4/0 Stranded Copper Conductor  
to  
#3 Reinforcing Bar**

**Description**

---

4/0 Stranded Copper Conductor to #3 Reinforcing Bar  
Tee of Horizontal Thru Reinforcing Steel & Horizontal Tap Cables

(2) #WRPSLV Wrap Sleeves required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US115	NUWTUBE115	MH1