



RB52SB

**#2 Solid Copper Conductor
to
#5 Reinforcing Bar**

Description

#2 Solid Copper Conductor to #5 Reinforcing Bar
Tee of Horizontal Thru Reinforcing Steel & Horizontal Tap Cables

(2) #WRPSLV Wrap Sleeves required per weld

| UltraShot Weld Metal | NUWTube Weld Metal | Mold Handle |
|----------------------|--------------------|-------------|
| US90 | NUWTUBE90 | MH1 |