



RO42SB

#2 Solid Copper Conductor to #4 Reinforcing Bar

Description

#2 Solid Copper Conductor to #4 Reinforcing Bar
Cross of Horizontal Cable Lapped Over Horizontal Reinforcing Steel

(2) #WRPSLV Wrap Sleeves required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US90	NUWTUBE90	MH1