



**R054B**

**#4 Stranded Copper Conductor  
to  
#5 Reinforcing Bar**

**Description**

---

#4 Stranded Copper Conductor to #5 Reinforcing Bar  
Cross of Horizontal Cable Lapped Over Horizontal Reinforcing Steel

(2) #WRPSLV Wrap Sleeves required per weld

UltraShot Weld Metal	NUWTube Weld Metal	Mold Handle
US65	NUWTUBE65	MH1